


## **HEADTUBE FRONT VIEW**



## **DOWNTUBE UNDER VIEW**



## **DOWNTUBE TOP VIEW**

center application tape with the headtube ST 50 adjust application tape from the welding (+/- 3 mm)